



UCWL UDAIPUR CEMENT WORKS LIMITED

UCWL/ENV/BMW/2023-24/ 3337

23rd May, 2023

The Regional Officer

Rajasthan State Pollution Control Board, F-470, Madri Industrial Area, Udaipur-Rajasthan - 313022

Sub:

Submission of Annual report in Form-IV for the period From 01.01.2022 to 31.12.2022.

Ref:

Authorization Letter No. BMW/2021-2022/Udaipur/BMW/5

CtO File No. - F(BMW)/Udaipur(Girwa)/6215(1)/2021-2022/119-120

Dear Sir,

This has with reference to above subject & in compliance to authorization condition no. - 8, we are submitting herewith Annual report of our Occupational Health Centre situated at Shripatinagar, ČFA, P.O. Dabok, Udaipur (Rajasthan) – Pin - 313022, for the period 01st January 2022 to 31st December 2022.

We hope you will find the above in order.

Thanking you,

Yours faithfully

For Udaipur Cement Works Ltd.

Dr. R.P. Bimothi

(Chief Medical officer)

Encl: As above

Admin. Office: Nehru House, 4, Bahadur Shah Zafar Marg, New Delhi - 110002 | Phone: +91-11-66001142 / 66001112 |
Fax: +91-11-66001142 | Email: ucwl.customercare@ucwl.jkmail.com | Works & Regd. Office: Shripati Nagar, CFA, P.O. Dabok,
Udaipur - 313022, Rajasthan | Phone: +91-294-2655076 | Fax: +91-294-2655077 | Email: ucwl@ucwl.jkmail.com
CIN: L26943RJ1993PLC007267





Form – IV (See rule 13) ANNUAL REPORT

[To be submitted to the prescribed authority on or before 30th June every year for the period from January to December of the preceding year, by the occupier of health care facility (HCF) or common bio-medical waste treatment facility (CBWTF)]

| S. No. | Particulars | | | | |
|--------|--|---------|--|--|--|
| 1 | Particulars of the Occupier | | | | |
| | (i) Name of the authorized person (occupier or operator of facility) | : | Mr. Ram Prakash Bimothi, Chief Medical Officer (OHC) | | |
| | (ii) Name of HCF or CBMWTF | • | Industrial Occupational Health Centre, Udaipur Cement Works Ltd. (UCWL) | | |
| | (iii) Address for Correspondence | : | M/s UCWL, Shripatinagar, CFA, P.O. Dabok, Dist. Udaipur, Rajasthan, 313022 | | |
| | (iv) Address of Facility | : | M/s UCWL, Shripatinagar, CFA, P.O Dabok, Dist. Udaipur, Rajasthan, 313022 | | |
| | (v)Tel. No, Fax. No | : | | | |
| | (vi) E-mail ID | : | rpbimothi@ucwl.jkmail.com | | |
| | (vii) URL of Website | : | www.udaipurcement.com | | |
| | (viii) GPS coordinates of HCF or CBMWTF | : | Latitude: 24.650395, Longitude: 73.877552 | | |
| | (ix) Ownership of HCF or CBMWTF | : | M/s Udaipur Cement Works Ltd. (A subsidiary of JK Lakshmi Cement Ltd.) | | |
| | (x). Status of Authorization under the Bio- Medical Waste (Management and Handling) Rules | : | Authorization No.:- BMW/2021 2022/Udaipur/BMW/5 Valid upto :- 31/03/2026 | | |
| | (xi). Status of Consents under Water Act and Air Act | : | CTO No 2021-2022/Udaipur/8367 unde water act & Valid upto: 31/03/2026 | | |
| 2 | Type of Health Care Facility | | | | |
| | (i) Bedded Hospital | : | No. of Beds: 2 | | |
| | (ii) Non-bedded hospital Clinical Laboratory or Research Institute or Veterinary Hospital or any other) | • | Clinical Laboratory | | |
| | (iii) License number and its date of expiry | : | | | |
| 3 | Details of CBMWTF | : | | | |
| | (i) Number of health care facilities covered by CBMWTF | : | | | |
| | (ii) No. of Beds covered by CBMWTF | : | | | |
| | (iii) Installed treatment and disposal capacity of CBMWTF; | : | NA | | |
| | (iv) Quantity of bio medical waste treated or disposed by CBMWTF | : | | | |
| 4 | Quantity of waste generated or disposed | : | Yellow Category: 30.525 Kg | | |
| 4 | in Kg per Annum (on monthly average | | Red Category: 11.79 Kg | | |
| | basis) | | White: 1.9 Kg | | |
| | | | Blue Category: 21.372 Kg | | |
| | | | General Solid Waste: 80 kg | | |
| 5 | Details of the Storage, Treatment, Transp | ortatio | on, Processing and Disposal Facility | | |
| | (i) Details of the on-site storage | : | BMW stored in the colored dust bin specified. | | |

| 2 | | facility | | Capacity: 15 K | | | | |
|---|--|---|--------------------------------|--|----------------|--------------------|---|--|
| | | | | Provision of on-site storage: BMW waste stored not more than 2 days and hand over to CBMWTF. | | | | |
| | (ii) I | Disposal facilities | | | No of Units | Capacity Kg/day | Quantity Treated or disposed in kg Per annum | |
| | | | Incinerators | - | - | <u>-</u> | | |
| | | | | Plasma Pyrolysi s | | - | - | |
| | | | | Autoclaves | - | | - | |
| | | | | Microwave | | | - | |
| | | | | Hydroclave | - | | <u>-</u> | |
| | | | | Shredder | - | - | | |
| | | | | Needle tip cutter or destroyer | 1 | - | - | |
| | | | | Sharps | - | - | | |
| | | | | Encapsulation or concrete pit | - | _ | - | |
| | | | | Deep burial pits | - | - | <u>-</u> | |
| | | | | Chemical disinfection: | - | | - | |
| | | | Any other treatment equipment: | _ | - | - | | |
| | | Quantity of recyclable waste sold to authorized recyclers after treatment in Kg per annum | • | | | NA | | |
| | (iv) | No. of Vehicles used for collection and transportation of biomedical waste | : | | | | | |
| | (v) | sludge generated and dispose | | | Quar Gene | ntity erated | Where disposed | |
| | during the treatment of wastes in Kg per annum | | Incineration Ash ETP Sludge | | NA | NA | | |
| | (vi) | Name of the Common Bio- Medical Waste Treatment Facility Operator through which wastes are disposed of | | M/s En-vision | | | Pvt. Ltd. | |
| | (vii) | List of member HCF not handed over bio-medical waste. | | | | NA | | |
| 6 | commit | have bio-medical waste management tee? If yes, attach minutes of the s held during the reporting period | | Yes | | | | |

| | 1 4 1 as DMW | Yes | | |
|----|---|-----|--|--|
| | Details trainings conducted on BMW | 2 | | |
| | (i) Number of trainings conducted on BMW Management | 7 | | |
| | (ii) Number of personnel trained | 7 | | |
| | (iii) Number of personnel trained at the time of induction | | | |
| | (iv) Number of personnel not undergone any training so far | Nil | | |
| | (v) Whether standard manual for training is available? | Yes | | |
| 8 | Details of the accident occurred during the | Nil | | |
| | year S.Aidenta occurred | Nil | | |
| | (i) Number of Accidents occurred | Nil | | |
| | (ii) Number of persons affected | Nil | | |
| | (iii) Remedial Action taken (Pleaseattach details if any) | | | |
| | (iv) Any Fatality occurred, details | Nil | | |
| 9 | Are you meeting the standards of air Pollution from the incinerator? How many times in last year could not met the standards? | NA | | |
| | Details of Continuous online emission | NA | | |
| 10 | monitoring systems installed Liquid waste generated and treatment methods in place. How many times you have not met the standards in a year? | NA | | |
| 11 | Is the disinfection method or sterilization meeting the log 4 standards? How many times you have not met the standards in a | NA | | |
| 12 | year? Any other relevant information | Nil | | |

Certified that the above report is for the period from 01/01/2022 to 31/12/2022.

Date: 23/05/2023

Place: M/s UCWL, Shripatinagar, Dist.

Dabok, CFA, P.O.

Udaipur, 313022

Name and Signature of the Head of the Institution

(Dr. Rangakash Rmoshi